

LA-UR-21-22115

Approved for public release; distribution is unlimited.

Title: 16-460 Disposition Photos

Author(s): Quintana, Vicente M.

Intended for: Photographs

Issued: 2021-03-02

Disclaimer:

Los Alamos National Laboratory, an affirmative action/equal opportunity employer, is operated by Triad National Security, LLC for the National Nuclear Security Administration of U.S. Department of Energy under contract 89233218CNA000001. By approving this article, the publisher recognizes that the U.S. Government retains nonexclusive, royalty-free license to publish or reproduce the published form of this contribution, or to allow others to do so, for U.S. Government purposes. Los Alamos National Laboratory requests that the publisher identify this article as work performed under the auspices of the U.S. Department of Energy. Los Alamos National Laboratory strongly supports academic freedom and a researcher's right to publish; as an institution, however, the Laboratory does not endorse the viewpoint of a publication or guarantee its technical correctness.



16-460 Disposition Photos

February 2021



HE/Rad Non Detonable: Properly packaged HE/Rad Non Detonable waste awaiting on the profile from Waste Coordinator.





Room 101 Duct & Room 113 Duct: Work being done on removal of HE/Rad contaminated duct work in room 113 and 101.





Hallway Duct Work: Example of duct work throughout the building, both with asbestos residue from cork glue, and without.